










1




2




3




4





x3


A



x54

M6*40


B



x54

M15*9.5


C



x32

M3.5*14


D



x18

M5*40


E



x2

E1E2


F



x19


M8*40

G



x28


H



x3

10 inches

J



x12

M3*12

K




x6

K1K2


M3*16

$$H = CR + DR + CL + DL$$




1

A x4




2

F x4




3

B x4



4

A x6



5

C x10




E x1




E1

E2



6


B x2



7

A


x6



8


B

x6




9

F x6



10

B x4



11


C x6



H x3



CL




12



A x2





F x2



13




14



15

A


x6



16

B

x6



17


C x6



H x3




CR



18

A x4



19

C x10




E x1




E1

E2




20

B x4




21

A x8




22



B x4





23




24





25





26





27





28



29




30





x3

31





x3

32





x3

33





x3

34






x3



36

G

x28



37

K	x6
---	----



K1



K2

